Robotino: collision with the station during docking

04/18/2024 03:27:41

FAQ Article Print

Category:	Customer Sol.		**Votes:**	0
State:	public (all)		**Result:**	0.00 %
Language:	en		**Last update:**	07:01:29 - 06/02/2023

Keywords

Robotino docking

Problem (public)

What should one do if Robotino collides with the station during docking?

Solution (public)

Please adjust the aluminum dock profile mechanically, so that it is at the same height as IR sensors of Robotino. Please make sure that it is perpendicular.

The position and height of the aluminum dock profile can slide over the time due to load.