

Mitsubishi Robot: battery replacement set for 2010–2022 robots

05/16/2024 08:49:18

FAQ Article Print

Category:	Robotics	Votes:	0
State:	public (all)	Result:	0.00 %
Language:	en	Last update:	09:20:38 - 11/16/2023

Keywords

MPS Robot Station 8039313 8039312 8038848 2FB 2SDB

Problem (public)

What should be done if a Mitsubishi Robot shows the Low Battery error?

Solution (public)

Every MPS Robot Station is shipped with one set of replacement batteries. Further sets of this Mitsubishi Accessory are available using the PN [1]572162. This set contains one arm battery as well as one controller battery.

Maintenance requirements including this yearly duty to replace the batteries are part of the Mitsubishi documentation.

For further instructions, please visit chapter 5.3.1 of the controller and chapter 5.4 of the robot arm documentation, also see [2]<https://support.festo-didactic.com/otrs/public.pl?Action=PublicFAQZoom;ItemID=212>.

[1] <https://www.festo-didactic.com/int-en/learning-systems/factory-automation-industry-4.0/focus-trending-topics-i4.0/collaborative-robotics/battery-set-for-robot-rv-2sdb-rv-2fb.htm?fbid=aW50LmVuLjU1Ny4xNy4xOC4xODUyLjc2MTc>
[2] <https://support.festo-didactic.com/otrs/public.pl?Action=PublicFAQZoom;ItemID=212>;