

Mitsubishi robot re-calibration after battery change

04/26/2024 08:45:23

FAQ Article Print

Category:	Robotics	Votes:	0
State:	public (all)	Result:	0.00 %
Language:	en	Last update:	12:15:52 - 01/25/2023

Keywords

Mitsubishi Robot

Problem (public)

Origin data lost as battery died. Robot needs re-calibration.

Solution (public)

Please follow all the steps mentioned in the manual (Mitsubishi_OriginSet_Manual_v1_0_EN.pdf).